RESPONSE UNDER 37 C.F.R. § 1.116 EXPEDITED PROCEDURE EXAMINING GROUP 2100

Group Art Unit: 2121

Examiner: Sunray Chang

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

First Named

Inventor: Randy J. Longsdorf

Appln. No.: 10

10/719,163

Filed

November 21, 2003

For

PROCESS DEVICE WITH SUPERVISORY

OVERLAYER

Docket No.:

R11.12-0812

RESPONSE AFTER FINAL

Electronically Filed July 31, 2007

Mail Stop AF

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Sir:

This is in response to the Office Action dated June 1, 2007. With this response, claims 1-51 are presented for reconsideration and favorable action.

Section 6 the Office Action notes a definition of the term "retrofit". Further, the Office Action at Section 5 along with the fourth full paragraph on page 4 cites Eryurek '567 as showing the retrofit as set forth in the pending claims.

However, Applicant respectfully submits that the section of Eryurek '567 cited in the Office Action refers to the <u>replacement</u> of a component that is about to fail. The component that is being monitored and replaced in Eryurek '567 is not part of the diagnostic circuitry as set forth in the Eryurek '567 reference. In contrast, the invention as set forth in the pending claims, is directed to a providing the desired safety Integrity Level by retrofitting, or adding onto, an "older system".

Therefore, the claimed invention relates to retrofitting while the cited passages of Eryurek '567 relate to replacement of a part. Further still, the claimed invention is directed to retrofitting particular elements which are used to monitor operation of a component. In contrast, the cited

-2-

section of Eryurek '567 relates to directly monitoring the component. For example, Eryurek '567

does not show a device interface. Even when combined with the other cited references, Eryurek

'567 does not show the invention as set forth in the pending claims. It is believed that the present

application is in condition for allowance.

Additionally, the dependent claims include numerous elements which are not shown in

the cited references. These include, for example, monitoring data on a data bus, adding a sensor

which couples to the process device, controlling loop current based upon a safety failure, the use of

a watch dog circuit in a SIL configuration, monitoring errors in data stored in memory, interpolating

to correct data errors, an implementation in a feature module which couples to a sensor module, and

others.

In view of the above remarks, reconsideration and favorable action are respectfully

requested.

The Director is authorized to charge any fee deficiency required by this paper or credit

any overpayment to Deposit Account No. 23-1123.

Respectfully submitted,

WESTMAN, CHAMPLIN & KELLY, P.A.

By:_/Judson K. Champlin/

Judson K. Champlin, Reg. No. 34,797

900 Second Avenue South, Suite 1400

Minneapolis, Minnesota 55402-3319

Phone: (612) 334-3222 Fax: (612) 334-3312

JKC:rev